

SE00075 SENSOR SPECIFICATIONS

Dual-Axis Inclinometer

Range	$\pm 90^\circ$ ($\pm 25^\circ$ and $\pm 45^\circ$ measurement ranges also available)
Accuracy	0.15° at 25°C; 0.5° at -40°C to 80°C is typical
Operating Temperature	-40°C to 85°C (-40°F to 185°F)
Wake-Up Time	<1 s